

09/735 790

CG

DOCKET NO. 12762ROUS01U (NORT10-00128)  
Customer No. 33000

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 6,920,130 B2

Inventor(s) : Kenneth S. Ramey

Issued : July 19, 2005

Title : GATEWAY ADAPTER FOR A PBX SYSTEM

Attn: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction (in duplicate);
2. Certificate of Correction (in duplicate); and
3. A postcard receipt;

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Attn: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on 12/7/05.

Date: 12/7/05

Kathy Cedar  
Mailer  
Robert D. McCutcheon  
Robert D. McCutcheon  
Reg. No. 38,717

P.O. Drawer 800889  
Dallas, Texas 75380  
Phone: (972) 628-3600  
Fax: (972) 628-3616  
E-mail: [rmccutcheon@davismunck.com](mailto:rmccutcheon@davismunck.com)

*Certificate  
DEC 14 2005  
of Correction*

DEC 16 2005

DOCKET NO. 12762ROUS01U (NORT10-00128)  
Customer No. 33000

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 6,920,130 B2

Inventor(s) : Kenneth S. Ramey

Issued : July 19, 2005

Title : GATEWAY ADAPTER FOR A PBX SYSTEM

Attn: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**

Certain clerical or typographical errors were noted in the above identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

Respectfully submitted,

DAVIS MUNCK, P.C.

Date: 12/7/2005

  
\_\_\_\_\_  
Robert D. McCutcheon  
Registration No. 38,717

P.O. Drawer 800889  
Dallas, Texas 75380  
Telephone: (972) 628-3600  
Facsimile: (972) 628-3616  
E-mail: [rmccutcheon@davismunck.com](mailto:rmccutcheon@davismunck.com)

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,920,130 B2

DATED : July 19, 2005

INVENTOR(S) : Kenneth S. Ramey

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13, Claim 33, line 48, delete "racket" and insert -- packet --.

MAILING ADDRESS OF SENDER:  
Docket Clerk  
P.O. Drawer 800889  
Dallas, Texas 75380

PATENT NO. 6,920,130 B2

No. of additional copies

→ 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

DEC 16 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,920,130 B2

DATED : July 19, 2005

INVENTOR(S) : Kenneth S. Ramey

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13, Claim 33, line 48, delete "racket" and insert -- packet --.

MAILING ADDRESS OF SENDER:  
Docket Clerk  
P.O. Drawer 800889  
Dallas, Texas 75380

PATENT NO. 6,920,130 B2

No. of additional copies

→ 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

DEC 16 2005